

BT ID	Summary	Fixed Date	Fixed in Version	Type
101 (15)	By selecting, the layer should not be modified (bold)	28.09.2021	15.5.413	Bug
104 (15)	Grafic refresh is missing	28.09.2021	15.5.414	Bug
105 (15)	Grafic refresh is missing after deleting a 300	28.09.2021	15.5.415	Bug
106 (15)	PROCESSING, 013, Parameter "Tool Side" should not appear	28.09.2021	15.5.415	Bug
102 (15)	Link Icon setting does not work	26.09.2021	15.5.411	Bug
90 (15)	BTLx 2.1.0, PROCESSIDENT, ProcessID	21.09.2021	15.5.404	Bug
67 (15)	Definition view with 3 points should be improved	16.09.2021	15.5.397	Bug
94 (15)	Zoom, 5 axis contour zoom should be improved	16.09.2021	15.5.397	Bug
62 (15)	The Reference Side should be displayed by every view	15.09.2021	15.3.188	Bug
95 (15)	Userattribute, the limit of max 256 characters will be not checked	15.09.2021	15.5.390	Bug
92 (15)	Clic in graphic 1 contour shoud activate group instead Point	15.08.2021	15.5.347	Bug
93 (15)	EAccessViolation by Outline deleting	15.08.2021	15.5.347	Bug
91 (15)	unnecessary program abort by reading invalid BTLx file	21.07.2021	15.5.317	Bug
86 (15)	access violation read btlx with contour	15.07.2021	15.5.309	Bug
87 (15)	BTLX View - Contour FaceLimitedTop and FaceLimitedBottom missing	15.07.2021		Bug
88 (15)	BTLX Viewer, 040, Drillings are not reading the depth	15.07.2021	15.5.310	Bug
65 (15)	BTLx Userinterface - add Part UserReferencePlanes	13.07.2021	15.5.305	Bug
80 (15)	Extension of the Delphi/Cpp communication to CCU for processing parameter	13.07.2021	15.5.305	Feature
83 (15)	BTL can not be open and freez	09.07.2021	15.4.301	Bug

84 (15)	PROCESSING, Cut, Tool side false modelised since version 15.3.203	08.07.2021	15.4.299	Bug
81 (15)	Drilling, wrong P07 should not forbidd to open the BTL-file.	06.07.2021	15.4.295	Bug
79 (15)	All machine, Analyse project parameters project->Edition	29.06.2021	15.4.282	Bug
76 (15)	EAssertionFailed: FrmEZBaseDlg.pas, Zeile 11167 when I select 3 parts	17.06.2021	15.4.266	Bug
77 (15)	Outline, unidentified Parameter should not be shown	17.06.2021	15.4.266	Bug
54 (15)	RAWPART, the UID should be used only once	16.06.2021	15.4.262	Bug
75 (15)	EAssertionFailed: refresh not valid	14.06.2021	15.4.257	Bug
74 (15)	BTL should not be modified if not needed	11.06.2021	15.4.282	Bug
41 (15)	Sorting of processing should be improved	20.05.2021	15.4.218	Bug
64 (15)	BTLx user interface should be activated	12.05.2021	15.4.221	Feature
63 (15)	All machine, 010, direction of the cut should be the same as the shape	07.05.2021	15.3.202	Bug
61 (15)	USERFRIENDLINESS, Sawcut, side of Tool working not visible form end part	29.04.2021	15.3.187	Bug
48 (15)	PERFORMANCE, Project table, Improve activation of selected processing	28.04.2021	15.3.186	Bug
59 (15)	Treeview should be adapted to processing activation	26.04.2021	15.3.183	Feature
60 (15)	Assertion failed by adding UID for a Part allready in a rawpart	23.04.2021	15.3.178	Bug
56 (15)	PROCESSING 052, no more possible to open a BTL since Version 15.2.090	21.04.2021	15.2.148.52419	Bug
11 (15)	USERFRIENDLINESS, Project table, modify Row type translation	14.04.2021	15.3.160	Bug
55 (15)	Statistique should only available by BTL-Editor	14.04.2021	15.3.161	Bug
51 (15)	Deleting of free UIDs should be improved	12.04.2021	15.3.157	Feature
50 (15)	Deleting a nailing line should not give an error message	31.03.2021	15.2.142	Bug
49 (15)	EAccessViolation by Element deleting	30.03.2021	15.2.135	Bug
14 (15)	UID by Nesting in Hierarchy mode, UID selection should not jump to the project	29.03.2021	15.2.131	Bug
42 (15)	PERFORMANCE, Project table, option to activate or not processing selected	29.03.2021	15.2.131	Bug

44 (15)	PROCESSKEY 300 should not bring an error message	23.03.2021	15.2.118	Bug
31 (15)	PROCCESING 055, madexcept error with a dovetail in Release version	05.03.2021	15.1.047	Bug
28 (15)	Referenceside 5 and 6 should be shown in the the grafic interface	03.03.2021	15.2.092	Bug
32 (15)	BTLX shape is missing in BTLX Part UI	01.03.2021	15.2.088	Bug
3 (15)	GUID not unique should not be opened	24.02.2021	15.2.080	Bug
36 (15)	BTL 10.2 should be possible to open	18.02.2021	15.2.064	Bug
37 (15)	Icone of processing should not be red but green	18.02.2021	15.2.065	Bug
33 (15)	BTLx, length cut, wrong tool position	17.02.2021	15.2.064	Bug
35 (15)	BTLx, SawCut, wrong position of tool	17.02.2021	15.2.063	Bug
5 (15)	BTLx project should get a new icone	15.02.2021	15.2.057	Bug
7 (15)	Viewer should distinguish between BTL-Project and BTLx-Project	15.02.2021	15.2.057	Bug
29 (15)	BTLx Userinterface - changing MachiningLimits no working	28.01.2021	15.1.031	Bug
2 (15)	btlx 2.0 news and correction should be documented	26.01.2021	15.1.026	Bug
1 (15)	Hoops error in case of "(" in path Folder to "my documents"	19.01.2021	15.1.013	Bug
8 (15)	EExternalException: Assertion 'false' is false. (cahliginterfacewrapper.cpp - error_callback() - line 2592	07.12.2020	15.1.013	Bug
82 (15)	BTL and BTLx UID count > PART Count should be forbidden (redo)	12.11.2020	15.5.318	Feature
34 (15)	BTLx 2.0, Model for splines as linetype in contour (NURBS)	12.10.2020	15.2.059	Feature