

BT ID	Summary	Fixed Date	Fixed in Version	Type
39 (11)	Processing deleting should be improved	07.06.2018	11.0.210	Bug
40 (11)	BTLx, XSD on internet is no more found, not switch to local.	04.06.2018	11.0.204	Bug
36 (11)	PROCESSKEY 106 ProfileHead, wrong rounding	17.05.2018	11.0.175	Bug
37 (11)	Processkey 037, P09	17.05.2018	11.0.174	Bug
35 (11)	Processkey 030, wrong Model for P03>0 and P08<>β	16.05.2018	11.0.173	Bug
29 (11)	PROCESSING 020, missing P04 should be not warned as error	08.05.2018	11.0.169	Bug
27 (11)	OUTLINE, P09 should be not shown and not warned if missing	02.05.2018	11.0.157	Bug
20 (11)	PROCESSKEY 250, P13=10, P05 should be not displayed	25.04.2018	11.0.147	Feature
25 (11)	PREFABRICATION, Referenceside in ELEMENT requested	24.04.2018	11.0.150	Bug
21 (11)	USERFRIENDLINESS, copy a part should be improved	23.04.2018	11.0.139	Bug
24 (11)	PROCESSING 020, wrong shape between version 10 and 11	17.04.2018	11.0.135	Bug
23 (11)	X3D crash with optimisation	16.04.2018	11.0.132	Bug
18 (11)	TRANSFORMATION, open and close the pull down menu should not change the parameters' sorting	19.03.2018	11.0.094	Bug
1 (11)	PREFABRICATION, assertion failed by opening because of P13=200 and P14	16.03.2018	11.0.093	Bug
14 (11)	BTLx, GUID of Transformations should also displayed in BTL format	13.03.2018	11.0.088	Bug
13 (11)	BTLx, 250, P13=200 should be accepted and not converted	01.03.2018	11.0.077	Bug
11 (11)	BTLx, JackRafterCut, unavailable Angle should be replace by default value	28.02.2018	11.0.072	Bug
12 (11)	BTLx treeview, displaying link for 0300 should not change the name in bold	28.02.2018	11.0.075	Bug

124 (10)	PROCESSKEY 060, text	17.01.2018	10.0.457	Bug
123 (10)	BTL viewer crasch at exit with a BTLx file	15.01.2018	10.0.454	Bug
99 (10)	PROCESSING 250, missing P07 should be warned	16.12.2017	10.0.420	Bug
117 (10)	PROCESSKEY 250, reference plane should be free only by P08=0 and 100	15.12.2017	10.0.451	Bug
106 (10)	USERFRIENDLINESS, modification in pull down menu should be like parameter	01.12.2017	10.0.395	Feature
112 (10)	BTL-viewer and BTL-editor should be splitted	16.11.2017	10.0.373	Bug
113 (10)	X3D, Assertion fail at opening in camego, file x3d_model.cpp	16.11.2017	10.0.373	Bug
114 (10)	Assertion failed at btl opening (EExternalException)	16.11.2017	10.0.382	Bug
104 (10)	USERFRIENDLINESS, axonometry with right mouse click should work like the other buttons	08.11.2017	10.0.358	Feature
8 (11)	USERFRIENDLINESS, Transformations and UIDs should have their own group	31.10.2017	11.0.078	Feature
61 (10)	PART, UID's should be displayed as combobox + dynamic display of transformations	26.10.2017	10.0.341	Bug
103 (10)	USERFRIENDLINESS, add a Search box in treeview	26.10.2017	10.0.384	Bug
109 (10)	PROCESSKEY 250, wrong shape in case of partner contour	25.10.2017	10.0.339	Bug
82 (10)	USERFRIENDLINESS, the performance should be improved (Hoops lines deleted)	19.10.2017	10.0.327	Bug
97 (10)	SETUP should not be disturbed by virus scanner	16.10.2017	10.0.322	Bug
100 (10)	BTLx, show the Part - Transformation - GUID	02.10.2017	10.0.306	Bug
91 (10)	PROCESSKEY 250, Referenzplan are not read correctly	17.09.2017	10.0.291	Bug
92 (10)	PROCESSKEY 250, Change P03 of a contour with segment Typ2 change contour geometry	17.09.2017	10.0.323	Bug
96 (10)	BTLx assertion failed by reading	12.09.2017	10.0.285	Bug
95 (10)	Sorting of RAWPART and PARTS is wrong	11.09.2017	10.0.282	Bug
50 (10)	Processing Table, new Table is too slow	06.09.2017	10.0.276	Bug
93 (10)	PROCESSING 030, default value of P06 and P07 should be 90	05.09.2017	10.0.273	Bug

88 (10)	PROCESSING 250, check for segment's length =0 should be deactivated if P13=20	10.08.2017	10.0.250	Bug
41 (10)	PROCESSKEY 250, x3d, inside contour are not removed	28.07.2017	10.0.320	Bug
48 (10)	PROCESSKEY 050 Tenon, wrong shape in case of P14-P15=0	24.07.2017	10.0.227	Bug
51 (10)	PROCESSING 30, wrong shape in case of P04=53	24.07.2017	10.0.226	Bug
65 (10)	USERFRIENDLINESS, trider volume reference plane improve model	24.07.2017	10.0.227	Bug
71 (10)	PROCESSKEY 030, wrong shape because of P09 and P10	21.07.2017	10.0.225	Bug
72 (10)	PROCESSKEY 136, wrong shape by P09 > 0	21.07.2017	10.0.255	Bug
74 (10)	PROCESSKEY 138, wrong shape by P05=-1	20.07.2017	10.0.224	Bug
75 (10)	PROCESSKEY 012, P12 > part length should be shown	20.07.2017	10.0.224	Bug
19 (10)	BTLx, xsd, crash	18.07.2017	10.0.222	Bug
67 (10)	PROCESSKEY 010 Cut, False drawing (like double cut)	18.07.2017	10.0.221	Bug
77 (10)	PROCESSKEY 010, wrong shape	17.07.2017	10.0.221	Bug
79 (10)	PROCESSKEY 039 wrong shape if P08<>0	14.07.2017	10.0.219	Bug
83 (10)	PROCESSING 250, wrong shape if P13=20 and P15 defined only by Startpoint	12.07.2017	10.0.217	Bug
62 (10)	Import and show NURBS	07.07.2017	10.0.292	Bug
86 (10)	PROCESSING 250, assertion failed by reading	04.07.2017	10.0.208	Bug
69 (10)	SETUP should be checked because of BtlviewerUser.ini	27.06.2017	10.0.202	Bug
80 (10)	Statistic should show the processkey before designation	27.06.2017	10.0.201	Feature
70 (10)	PROCESSKEY 020 Birdsmouth, P07=9, wrong model	23.06.2017	10.0.198	Bug
66 (10)	USERFRIENDLINESS, debug menu should be not visible for BTL viewer	20.06.2017	10.0.192	Bug
63 (10)	PROCESSING 30, P04 should be checked (considering P09 and P10)	12.06.2017	10.0.181	Bug
58 (10)	PROCESSING 300, the copy should be forbidden	08.06.2017	10.0.181	Bug

59 (10)	Double UID and Reference plane should be better differenced	08.06.2017	10.0.181	Bug
55 (10)	USERFRIENDLINESS, the processing activated is not the selected one	06.06.2017	10.0.177	Bug
56 (10)	PROCESSKEY 250, if P08=0 or 100, P13 is master for the whole contour	06.06.2017	10.0.177	Bug
36 (10)	USERFRIENDLINESS, graphic setting's modifications should not need a restart	05.06.2017	10.0.174	Feature
49 (10)	BTLx, viewer does not show the content and does not bring any message	31.05.2017	10.0.179	Bug
45 (10)	BTLX 11 - XSD für BTLX Version 1.1 add local	22.05.2017	10.0.160	Feature
40 (10)	PROCESSING 250, P06 not equal to 0, wrong shape	18.05.2017	10.0.222	Bug
39 (10)	Message request by e-mail should be possible	16.05.2017	10.0.150	Feature
38 (10)	PROCESSKEY 252, BTLx, assertion fail at opening	15.05.2017	10.0.149	Bug
32 (10)	Statistic should contain the area of lap-joint	12.05.2017	10.0.151	Feature
33 (10)	USERFRIENDLINESS, SHIFT + CTRL for part selection is not working	11.05.2017	10.0.147	Bug
34 (10)	Statistic, Drilling are counted 2 times	10.05.2017	10.0.145	Bug
31 (10)	Statistic should be shown in a new tab	09.05.2017	10.0.148	Feature
27 (10)	PART: the information displayed in the treeview should be set	05.05.2017	10.0.141	Feature
29 (10)	x3d geometry is not read	28.04.2017	10.0.140	Bug
28 (10)	Processing Table, new Table more modern for BTL 10	26.04.2017	10.0.158	Bug
17 (10)	BTLx, xsd file address should be shown in the info windows	25.04.2017	10.0.120	Feature
16 (10)	BTLx, error message because of XMLDoc not valid	24.04.2017	10.0.117	Bug
18 (10)	BTLx, xsd -file download and xsd-file setting should be possible (internal Version)	24.04.2017	10.0.117	Bug
20 (10)	USERFRIENDLINESS, after copy/paste the copy should be activated	20.04.2017	10.0.114	Bug
23 (10)	Processing Table should match the design of the processing area	13.04.2017	10.0.106	Feature
21 (10)	USERFRIENDLINESS, difference between button activated and deactivated should be more clear	11.04.2017	10.0.101	Feature

22 (10)	PROCESSKEY 055, wrong P12 between BTL and BTLx	06.04.2017	10.0.088	Bug
24 (10)	BTLx, model for birdsmouth is wrong	06.04.2017	10.0.087	Bug
25 (10)	USERFRIENDLINESS, show a Triedre volum for specific reference Plane	04.04.2017	10.0.087	Bug
14 (10)	PROCESSING 30, btl versus btx LeadAngleParallel and LeadInclinationParallel	27.03.2017	10.0.088	Feature
10 (10)	PREFABRICATION, processing added are not shown and need a manually refresh	07.03.2017	10.0.053	Bug
12 (10)	USERFRIENDLINESS, processing selected in the grafic should be also activated	07.03.2017	10.0.053	Bug
11 (10)	PROCESSING 900, processing added need a refresh	06.03.2017	10.0.052	Bug
8 (10)	Crash by BTL-reading	28.02.2017	10.0.046	Bug
3 (10)	BTL Viewer, donwload without Licence should check a new Folder in Lignocam Website	22.02.2017	10.0.125	Bug